


CORNER RECORD

COUNTY OF MONO T. 3S R. 27E SEC. 34 MERIDIAN CALIFORNIA
 CORNER TYPE: GOV'T. CORNER ☐ MEANDER ☐ RANCHO ☐ CONTROL ☐ OTHER ☒
 CORNER IDENTIFICATION - DATE OF VISIT June 20 1989



SE. Corner, Lot 31B, Sierra Valley Sites I, MB 4, Pg. 1

CORNER - LEFT AS FOUND ☐ FOUND AND TAGGED ☐ REESTABLISHED OBLITERATED CORNER ☐ REBUILT ☒

PHYSICAL DESCRIPTION OF CORNER FOUND: EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH

Found 1/2" iron pipe per MB 4/1, bent over. Reset corner by direct replacement at root position. Checked record distance to Southwest corner.

PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED


Set 1" iron pipe tagged LS 4587.

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST ☐ SECOND ☐ THIRD ☐

STATIONS USED: NGS (USC & GS) ☐ STATE ☐ COUNTY ☐ OTHER ☐ STATION _____ STATION _____

ZONE _____ ELEVATION _____ NORTHINGS (Y) _____ EASTINGS (X) _____

SKETCH: (Include reference tie or witness points, remarks and topo of area)



LEGEND

- Fd. 3"x3" idwood hub per MB 1/26, set in concrete, in lieu of 1/2" rebar in conc. per MB 4/1. Original corners in this subdivision are typically "bush size" 2x2 hubs: 2 1/2"x2 1/2" or 3"x3"
 - Fd. 1/2" I.P. bent, replaced with 1" I.P. tagged LS 4587 at root position
- (R) Record data per MB 4/Pg. 1

JN 74

SURVEYOR'S CERTIFICATE

THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE LAND SURVEYORS ACT ON August 20 1989

SIGNED: _____

L.S. or R.C.E. No.: 4587

SEAL

COUNTY SURVEYOR'S CERTIFICATE

THIS CORNER RECORD WAS RECEIVED 2-28 19 90 AND EXAMINED AND FILED 5-11 19 90

BY: Chris Threlkeld

TITLE: MONO COUNTY SURVEYOR

DOCUMENT No. 3527-34-37

STATEMENT ON BACK OF SHEET

YES ☐ NO ☒